

Menu


HISTORY FILE MAP for year 2002

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



119.14:51-15:03: 12m realtime data lost due to DSS-54 Receiver Control Computer (RCC) problem.

119.16:47-16:58: 11m realtime data lost due to DSS-54 Receiver out of lock. DR M100692 refers.